


1/2

Fig.1

(PRIOR ART)



Technical drawing of a cross-section of a mechanical assembly, labeled 5. The drawing shows a central component 49 with a cross-hatched pattern, flanked by components 45 and 47. A component 56 is on the left, and a component 43a is on the right. A component 43b is at the bottom right. Dimensions H, R, and s are indicated. The drawing is labeled 5 at the bottom left.

Fig. 2

5T

29

5V

27

33

31

5G